




We Show Up



We Bring It



We Do It Right

Turn Style Consignment

Turn Style Consignment in Maple Grove, MN is a clothing, accessories and home consignment store.

THE CHALLENGE

Settling issues occurred in the summer of 2021 during sidewalk construction. This resulted in two broken corner windows at the Maple Grove Turn Style location.

OUR SOLUTION

Brin Glass Service provided and installed the necessary windows to replace the broken corner pieces.

RESULTS ACCOMPLISHED

Brin Glass Service provided the glass and our glaziers worked quickly to install the pieces, so the store was not impacted by Minnesota winter drafts. The new windows also improved the building's security and enhanced the professional appearance of this retail store.

Why was Brin Glass best suited for the work?

Brin Glass Service was able to be on-site quickly to assess the damage and provide a solution to the store manager. Our glaziers had the skills to beautifully install the new glass pieces for the store.

Turn Style Consignment Maple Grove

Contact

Nicole Nelson- Store Manager

Project Start February 2022

Project End February 2022

Executed By Brin Glass Service



Broken Glass due to settling issues



Brin Glass Service Glaziers made the repairs necessary