

SUCCESS STORY



Providing an Emergency Makeover

This was a large reconstruction of a salon storefront that was damaged when a client drove through the front of the building. Thankfully, the accident happened before the salon opened for the day, so nobody was inside and there were no injuries. Brin Glass Service sprang into action when they received the emergency call. We immediately headed out to the salon location in Chaska, MN to board-up, measure and order glass for this property.

THE CHALLENGE

The customer needed to act quickly, as this incident impacted daily business operations and caused safety concerns. The entire storefront, including the door and frame, were impacted.

OUR SOLUTION

Since Brin Glass Service offers a 24-hour emergency service, their glaziers were able to quickly schedule an onsite visit to secure and measure what needed to be replaced.

RESULTS ACCOMPLISHED

Brin Glass Service was able to effectively measure and order the necessary materials to help Sulit Salon get back to business as quickly as possible.

Why was Brin Glass best suited for the work?

Due to Brin Glass Service's 24-hour emergency service offering, combined with their ability to leverage resources from other divisions within the Brin family of companies, they were able to order the necessary materials quickly and effectively.

Sulit Salon

Contact Jessica Trebil, Property Manager, SDC Retail Properties

Project Start July 2022 Project End October 2022

Executed By Brin Glass Service



Before and After









